

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 302848

County Stark Township Plain Section of Township 22
Owner Norman Gastman Address 5230 Lomalinda N. E. Canton 4,0.
Location of property 915 52nd St. N. E. Canton 4, Ohio

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4 in.</u> Length of casing <u>70 ft.</u>	Pumping Rate <u>12</u> G.P.M. Duration of test <u>2</u> hrs.
Type of screen _____ Length of screen _____	Drawdown <u>30</u> ft. Date <u>Nov. 1, 1963</u>
Type of pump _____	Static level-depth to water <u>55</u> ft.
Capacity of pump _____	Quality (clear, cloudy, taste, odor) <u>Clear</u>
Depth of pump setting _____	Pump installed by _____
Date of completion <u>Nov. 1, 1963</u>	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
mud	0 Feet	10 Ft.	
mud & gravel	10	15	
mud	15	25	
soft shale	25	43	
lime	43	45	
shale	45	63	
lime	63	68	
shale	68	100	
shale	100	170	

S.
See reverse side for instructions

Drilling Firm Rhoades Drilling Co., Inc. Date Nov. 4, 1963
Address Box 474 Canal Fulton, Ohio Signed _____