

N.D.

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

(23)
No 302912

County Seneca Township Reed Section of Township _____
Owner William E. Werty Address R.R. 2, Republic, Ohio
Location of property 1/4 mi. South of Republic 3/4 mile East 6 miles

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 74 ft.
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 15 G.P.M. Duration of test 2 hrs.
Drawdown 5 ft. Date Dec. 4, 1963
Static level-depth to water 40 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Yellow clay</u>	<u>0 Feet</u>	<u>10. Ft.</u>
<u>Blue clay</u>	<u>10.</u>	<u>63 ft.</u>
<u>Sand.</u>	<u>63</u>	<u>74 ft.</u>
<u>Brown limestone</u>	<u>74</u>	<u>81 ft.</u>
<u>Water 79 ft.</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm R. C. Pittman
Address R.R. 2, Tiffin, Ohio

Date Dec. 4, 1963
Signed Merrill D. Lawrence

(23)

LOCATED