

WELL LOG AND DRILLING REPORT

5 ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 303312

County Wayne Township Milton Section of Township 9

Owner Mabel Mishack Address 5705 H 1 N 8 - 0

Location of property Stirling Ohio

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 129 ft
Type of screen - Length of screen -
Type of pump piston
Capacity of pump 5 GPM
Depth of pump setting -
Date of completion 4-5-64

BAILING OR PUMPING TEST

Pumping Rate 30 G.P.M. Duration of test 3 hrs.
Drawdown 0 ft. Date 4-5-64
Static level-depth to water 10 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Owner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	6 Ft.
<u>top soil & fill</u>		
<u>marl & gravel</u>	<u>6</u>	<u>24</u>
<u>Glacial Drift</u>	<u>24</u>	<u>100</u>
<u>Sandy Gravel</u>	<u>100</u>	<u>122</u>
<u>Gravel</u>	<u>122</u>	<u>129</u>
<u>Well is 129 ft deep</u> <u>from top of casing</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.
504
W. MAHON ST
5705 H 1 N 8
E.
S.

See reverse side for instructions

Drilling Firm NeVore Drilling

Address Genville

Date 4/6/64

Signed J. H. NeVore

Boys 3 64

5