

WEI LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

89
No. 303316

County Franklin Township Franklin Section of Township 1

Owner Coy Cutton Address Co Rd 52 S of 162

Location of property Co Rd 52 S of 162

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 45
Type of screen 20 Length of screen 20
Type of pump Sum
Capacity of pump 400 G.P.H.
Depth of pump setting 60
Date of completion July 20/64

BAILING OR PUMPING TEST

Pumping Rate 127 G.P.M. Duration of test 1 hrs.
Drawdown 0 ft. Date July 20
Static level-depth to water Station ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by DeVore

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

.....Ft.

Soil

0

3

Sandy clay

3

32

Sand

32

46

Shale

46

55

Sand & Gravel

55

65

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N. 1020

CR 5-2

W.

E. 162

SR 5-1

S.

See reverse side for instructions

Drilling Firm DeVore Drilling

Date July 28/64

Address Seville Ohio

Signed J. H. DeVore

Box 364

LOCATED
241