

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 303317

County Medina Township Gudford Section of Township _____
Owner Paul Hosack Address _____
Location of property Co R 10 55-500 ft S of Co 119

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 50
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 20 G.P.M. Duration of test 2 hrs.
Drawdown 0 ft. Date July 21
Static level-depth to water 30 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Joe Vore

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.
<u>Soil</u>	<u>0</u>	<u>2</u>
<u>Rock & Clay</u>	<u>2</u>	<u>22</u>
<u>Shale</u>	<u>22</u>	<u>45</u>
<u>Sandstone</u>	<u>45</u>	<u>60</u>
<u>& Shale</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Joe Vore Drilling Date July 28 1964
Address Leville Ohio Signed Joe Vore

LOCATED
69