

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 303662

County Clarke Township German Section of Township 36-57-20
Owner John W. Rutledge Address 3850 Darnell Rd
Location of property 1/4 mi. N of Laurensville on Willow Rd

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 132
Type of screen None Length of screen —
Type of pump No pump yet
Capacity of pump —
Depth of pump setting —
Date of completion Dec 18 - 1967

BAILING OR PUMPING TEST


Pumping Rate 10 G.P.M. Duration of test 5 hrs.
Drawdown 50 ft. Date —
Static level-depth to water 40 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by —

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay	0 Feet	20 Ft.
Gravel	20	28
Blue Clay	28	55
Sand	55	65
Clay	65	71
Sand	71	80
Clay	80	110
Gravel	110	121
Clay	121	132
Limestone	132	140

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm C.S. Burroughs

Date Dec 18 1967

Address 4818 Troy Rd

Signed C.S. Burroughs

Springfield 40502

B53