

WEI LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 304633

County Cuyahoga Township Bedford Section 14 of Township 14

Owner J. Gannon Address 7728 Sunshine

Location of property Same

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 50'
Type of screen _____ Length of screen _____
Type of pump deep well
Capacity of pump _____
Depth of pump setting 160'
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 7 G.P.M. Duration of test 2 hrs.
Drawdown _____ ft. Date 8-27-65
Static level-depth to water 60 ft.
Quality (clear, cloudy, taste, odor) good
Pump installed by Herbert P. By

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	.../...Dft.
<u>Clay</u>	<u>10</u>	<u>40</u>
<u>Shale</u>	<u>40</u>	<u>140</u>
<u>Sandstone</u>	<u>140</u>	<u>195</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Herbert P. By
Address 7 Bruce

Date 8-27-65
Signed Herbert P. By

(455)