

WELL LOG AND DRILLING REPORT

375

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 305530

County Stark Township Plain Section of Township 7

Owner Harvey B. Rose Address 1024 N. Main Street N. Canton 20,0.

Location of property 1024 N. Main Street North Canton, Ohio

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST	
Casing diameter <u>6 in.</u> Length of casing <u>35 1/2 ft.</u>			Pumping Rate <u>16</u> G.P.M. Duration of test <u>2</u> hrs.	
Type of screen..... Length of screen.....			Drawdown <u>none</u> ft. Date <u>Dec. 20, 1963</u>	
Type of pump <u>submergible</u>			Static level-depth to water <u>15</u> ft.	
Capacity of pump <u>20 g.p.m.</u>			Quality (clear, cloudy, taste, odor) <u>clear</u>	
Depth of pump setting <u>25 ft.</u>				
Date of completion <u>Dec. 20, 1963</u>			Pump installed by <u>Rhoades Drilling Co., Inc.</u>	
WELL LOG			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
<u>Glacial formation</u>	<u>0 Feet</u>	<u>35 1/2 Ft.</u>		

See reverse side for instructions

Drilling Firm Rhoades Drilling Co., Inc.

Date Jan. 8, 1964

Address Box 474 Canal Fulton, Ohio

Signed