

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 305732

County Shelby Township Turtle Creek Section of Township
Owner Cletus Schmitzing Address R#4 - Sidney, Ohio
Location of property 1/2 mile west of Rt 29 on south side of Rt 705.

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>5 5/8"</u> Length of casing <u>76 1/2'</u>	Pumping Rate <u>30</u> G.P.M. Duration of test <u>1 1/2</u> hrs.
Type of screen <u> </u> Length of screen <u> </u>	Drawdown <u> </u> ft. Date <u>12/19/64</u>
Type of pump <u> </u>	Static level-depth to water <u>65</u> ft.
Capacity of pump <u> </u>	Quality (clear, cloudy, taste, odor) <u>clear</u>
Depth of pump setting <u> </u>	
Date of completion <u> </u>	Pump installed by <u>Ralph Thoman</u>

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
<u>Top Soil</u>	<u>0 Feet</u>	<u>1</u> Ft.	
<u>Clay & Gravel</u>	<u>1'</u>	<u>69'</u>	
<u>Sand & Gravel</u>	<u>69'</u>	<u>72'</u>	
<u>Limestone</u>	<u>72'</u>	<u>115'</u>	

See reverse side for instructions

Drilling Firm Richard L. Bursling
Address Huntsville, Ohio

Date Dec. 21, 1964
Signed Richard L. Bursling

93
LOCATED

93