

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 305733

County Shelby Township Union Section of Township —Owner Mrs. Nora Neiland Address Anna, OhioLocation of property 1/4 mile west of Old St Rt 25 on north side of St. Rt 274

CONSTRUCTION DETAILS

Casing diameter 4 1/4" Length of casing 74 1/2'
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —
Date of completion —


BAILING OR PUMPING TEST

Pumping Rate 12 G.P.M. Duration of test 24 hrs.
Drawdown — ft. Date 12/24 + 12/25 - '64
Static level-depth to water 30 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by Ralph Thoman

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Top Soil</u>	<u>0 Feet</u>	<u>1 Ft.</u>
<u>Clay, Gravel + Sand</u>	<u>1'</u>	<u>33'</u>
<u>Sand + Gravel</u>	<u>33'</u>	<u>37'</u>
<u>Clay</u>	<u>37'</u>	<u>48'</u>
<u>Sand + Gravel</u>	<u>48'</u>	<u>54'</u>
<u>Clay + Gravel</u>	<u>54'</u>	<u>68'</u>
<u>Sand + Gravel</u>	<u>68'</u>	<u>73'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

See reverse side for instructions

Drilling Firm Richard L. Bushong
Address Huntsville, OhioDate Dec. 30, 1964
Signed Richard L. Bushong