

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 305737

County Shelby Township Jackson Section of Township 4

Owner Robert L. Lehmkuhl Address Rt 1 - Minster, Ohio

Location of property 3 miles west of Mc Cartysville on Rt 119 on north side of road.

CONSTRUCTION DETAILS

Casing diameter 5 5/8" Length of casing 68'
Type of screen none Length of screen -
Type of pump -
Capacity of pump -
Depth of pump setting -
Date of completion -

BAILING OR PUMPING TEST


Pumping Rate 36 G.P.M. Duration of test 3 hrs.
Drawdown none ft. Date 4/13/65
Static level-depth to water 32 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by Ralph Thoman

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Top Soil</u>	<u>0 Feet</u>	<u>1</u> Ft.
<u>Clay</u>	<u>1'</u>	<u>18'</u>
<u>Clay, Gravel + Sand</u>	<u>18'</u>	<u>65'</u>
<u>Limestone</u>	<u>65'</u>	<u>172'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Richard L. Bushong
Address Huntersville, Ohio

Date April 17, 1965
Signed Richard L. Bushong

