

32

WEI LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 306138

County COLUMBIANA Township WAYNE Section of Township 23

Owner LAWERANCE ARMSTRONG Address R. D. #1, LISBON, OHIO

Location of property

CONSTRUCTION DETAILS		BAILING OR PUMPING TEST	
Casing diameter <u>6 1/4</u>	Length of casing <u>22</u>	Pumping Rate <u>?</u> G.P.M.	Duration of test <u>?</u> hrs.
Type of screen	Length of screen	Drawdown <u>?</u> ft.	Date <u>?</u>
Type of pump		Static level-depth to water <u>7</u> ft.	
Capacity of pump		Quality (clear, cloudy, taste, odor)	
Depth of pump setting			
Date of completion		Pump installed by	

WELL LOG			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
YELLOW CLAY	0 Feet	15 Ft.		
SAND ROCK	15	28		
SLATE	28	42		
COAL	42	45		
SLATE	45	50		
SAND ROCK	50	78		
SANDY SHALE	78	130		
SAND ROCK	130	187		
Slate	187	193		

Drilling Firm O. E. MILLER DRILLING Date JULY 18, 1966

Address P. O. BOX 78, EAST LIVERPOOL, O. Signed O. E. MILLER

LOCATED

(34)