

6

WELL LOG AND DRILLING REPORT

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 306147

County COLUMBIANA Township WASHINGTON Section of Township 18

Owner LEWIS A. WHITAKER Address SALINVILLE OHIO, R. D. 2,

Location of property RT. # 39,

CONSTRUCTION DETAILS		BAILING OR PUMPING TEST	
Casing diameter <u>6$\frac{1}{2}$</u>	Length of casing <u>23'</u>	Pumping Rate.....G.P.M.	Duration of test.....hrs.
Type of screen.....	Length of screen.....	Drawdown.....ft.	Date.....
Type of pump..... <u>SUBMERSIBLE</u>		Static level-depth to water..... <u>30 FT.</u>	ft.
Capacity of pump..... <u>5 G. P. M.</u>		Quality (clear, cloudy, taste, odor).....	
Depth of pump setting..... <u>87 FT.</u>		<u>BAILER TEST 1$\frac{1}{2}$ G. P. M.</u>	
Date of completion.....		Pump installed by..... <u>O. E. MILLER</u>	

WELL LOG			SKETCH SHOWING LOCATION	
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.	
SHALE	0 Feet	<u>30</u> Ft.	N. W. E.	
SANDY SHALE	30	40		
Sand ROCK	40	75		
SHALE	75	90		
SAND ROCK	90	103		
WATER 40 TO 45 FT.				