

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

7222
126
No 306259.

County CARROLL Township Brown Section of Township
Owner William MASSEY Address RD. 2 MINERVA, O
Location of property 1/2 mile west on County line rd. from Minerva

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing 144'
Type of screen — Length of screen —
Type of pump 1/2 HP 20 stage Submersible
Capacity of pump 300 gal. per Hr.
Depth of pump setting 200
Date of completion Aug 27, 1964

BAILING OR PUMPING TEST


Pumping Rate 5 G.P.M. Duration of test 1 hrs.
Drawdown 100 ft. Date
Static level-depth to water 100 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by C. Ault/Jalter

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
TOP SOIL	0 Feet	5 Ft.
SANDSTONE	5	30
SHALE	30	50
SLATE	50	70
COAL	70	71
CLAY	71	76
SLATE	76	100
CLAY	100	125
SLATE	125	134
COAL	134	135
SANDSTONE	135	148
SLATE	148	217

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Charles Ault/Jalter Drilling Date Aug 27 1964
Address 15399 Lincoln St SE Minerva, O Signed C. Ault/Jalter

90