

WEI LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 306260

County COLUMBIANA Township WEST Section of Township _____
Owner MR. B. BRYAN Address EAST ROCHESTER, OHIO
Location of property one half mile south of East Rochester

CONSTRUCTION DETAILS

Casing diameter 5 3/8" Length of casing 52' 7"
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —
Date of completion Oct. 23, 1964

BAILING OR PUMPING TEST


Pumping Rate 20 G.P.M. Duration of test 1 hrs.
Drawdown 10 ft. Date Oct. 23, 1964
Static level-depth to water 60 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by —

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
TOP SOIL	0 Feet	3 Ft.
SAND AND GRAVEL	3	50
BLACK SLATE	50	51
SAND STONE	51	80

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Charles Aultfather Drilling Date Oct. 23, 1964
Address RD #3 Minerva, O Signed C. Aultfather