

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 306878

County MEDINA Township LITCHFIELD Section of Township
Owner A. L. Ruffe Stump Address RI, LITCHFIELD, Ohio
Location of property 1 MI. SOUTH of ST. Hwy. 18 on West Side of St. Hwy 76

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 32'-11"
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting 65'
Date of completion June 30 1967

BAILING OR PUMPING TEST


Pumping Rate 20 G.P.M. Duration of test — hrs.
Drawdown — ft. Date June 30/67
Static level-depth to water 15 ft ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Owner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	3 Ft.
Clay	3	12'
Loam + sand	12	21
Clay + sand	21'	26
Gravel	26'	32'-11" W.
Clay Gravel	32'-11"	40'
Stone	40'	70'
Gray shale	61'	
Water		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm J. Yarnish

Address R. B. Elgin

Date June 30 1967

Signed J. Yarnish

LOCATED
92