

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 307500

OK - Sub
w/ M 2

County WASHINGTON Township DUNHAM Section of Township CENTER w/ M 2

Owner FRANK Roush Address VAN VENT O

Location of property RT 76 AT VETO O

CONSTRUCTION DETAILS

Casing diameter 8" Length of casing 13'
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....
Date of completion 10/12/65

BAILING OR PUMPING TEST


Pumping Rate 1 G.P.M. Duration of test..... hrs.
Drawdown..... ft. Date.....
Static level-depth to water 15 ft.
Quality (clear, cloudy, taste, odor).....
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
MUD	0 Feet	12 Ft.
SANDSTONE	12	32
SLATE W	32	57
RED	57	79
SLATE	79	<u>95</u>
WATER 38'		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm LARRY S DAILEY

Address RT 2 Marengo

Date 11/1/65

Signed Larry S Dailey