

# W.L LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL  
OR TYPEWRITER  
DO NOT USE INK.

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
1562 W. First Avenue  
Columbus 12, Ohio

59  
No 307637

County Licking Township Licking Section of Township

Owner Lee Angle Address Conway Drive

Location of property Village Vista - Park - Yoway between SR-79 & Cty Rd 204  
on TWP Rd-308

## CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 70  
Type of screen per Length of screen 3 ft  
Type of pump -  
Capacity of pump -  
Depth of pump setting -  
Date of completion -

## BAILING OR PUMPING TEST

Pumping Rate 70 G.P.M. Duration of test 4 hrs.  
Drawdown 20 ft. Date Oct - 63  
Static level-depth to water 40 ft.  
Quality (clear, cloudy, taste, odor) clear  
Pump installed by

## WELL LOG

| Formations<br>Sandstone, shale, limestone,<br>gravel and clay | From   | To       |
|---------------------------------------------------------------|--------|----------|
|                                                               | 0 Feet | .....Ft. |
| clay                                                          | 0      | 60       |
| sand                                                          | 60     | 67       |
| gravel                                                        | 67     | 70       |
| Water                                                         | 60     |          |

## SKETCH SHOWING LOCATION

Locate in reference to numbered  
State Highways, St. Intersections, County roads, etc.

