

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 307750

County Stark Township Plain Section of Township 4
Owner Robert W Bowers 3/4 mi W. of Euro Mt Pleasant Rd.
Address Turn S. on Elmhorst
Location of property 7960 Elmhorst Ave. N.W. North Canton 20 Ohio

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4"</u> Length of casing <u>46 ft</u>	Pumping Rate <u>10</u> G.P.M. Duration of test _____ hrs.
Type of screen _____ Length of screen _____	Drawdown <u>5</u> ft. Date <u>7-25-64</u>
Type of pump _____	Static level-depth to water <u>30</u> ft.
Capacity of pump _____	Quality (<u>clear</u> , cloudy, taste, odor) _____
Depth of pump setting _____	
Date of completion _____	Pump installed by _____

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
Yellow clay & Gravel	0	25 ft	
Gray clay & sand	25	40	
Gray shale	40	55	
Sand rock	55	60	
Gray shale	60	62	
Total depth of well		62 ft	

See reverse side for instructions

Drilling Firm P. L. Graham
Address 1174 Mt Pleasant Rd. N.W.
North Canton 20 Ohio

Date 7-25-64
Signed Parker Graham