

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 309850

County Jeff Township Salon Section of Township 7 Lat 13
Owner Quinn Bethel Address Sturtevant
Location of property 152 South 646

CONSTRUCTION DETAILS

Casing diameter 4 Length of casing 37
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST


Pumping Rate G.P.M. Duration of test hrs.
Drawdown ft. Date
Static level-depth to water 85 ft.
Quality (clear, cloudy, taste, odor)
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
<u>Shale & Limestone</u>		<u>26</u>
<u>Gray shale & Limestone</u>	<u>26</u>	<u>65</u>
<u>Sandy</u>	<u>45</u>	<u>115</u>
<u>Heavy shale</u>	<u>115</u>	<u>145</u>
<u>water</u>		
<u>110</u>		
<u>Iron 85</u>		
<u>Good</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm John S. 11
Address

Date Oct 65
Signed John S. 11

144H