

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 309951

County Montgomery Township Miami Section of Township 4
Owner Larry Schenck Address Route #1 Germantown, Ohio
Location of property 3/10 Mile East of State Route #4 on Manning Road

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 5 7/8 Length of casing 130'
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —
Date of completion Aug 8, 1964


Pumping Rate 12 G.P.M. Duration of test 1 hrs.
Drawdown 5 ft. Date Aug 8, 1964
Static level-depth to water 92' ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by —

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
Brown Clay & Gravel	0 Feet	8 Ft.
Dry Sand & Gravel	8	87
Hardpan & Gravel	87	109
Sand & Gravel	109	118
Grey Clay	118	130
Sand & Gravel	130	
Water at 109'		
" " 130'		
1729		

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm **THOMAS WELL DRILLING**
3848 MIAMISBURG-CENTERVILLE RD.
Address **MIAMISBURG, OHIO**

Date Aug. 10, 1964
Signed Charles R. Thomas