

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 310466

County Shelby Township Huntington Section of Township 1

Owner Carl L. Miller Address Rt. 3, Wellsburg, W. Va.

Location of property 1 mi. N. of Huntington, W. Va. on Rte. 1, 1/2 mi. N. of
Clark

CONSTRUCTION DETAILS

Casing diameter 10" I.D. Length of casing 28'
Type of screen none Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST


Bailed
Pumping Rate 10 G.P.M. Duration of test 1 hrs.
Drawdown Bottom ft. Date 8-12-65
Static level-depth to water 13 ft.
Quality (clear, cloudy, taste, odor)
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	24 Ft.
		28'
		30'
Water 24'		
Bottom 3'		
14' 2" sand		
limestone 13' 2" sand		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm J. Goddard Drilling

Date 8-12-65

Address Rt. 3, Wellsburg, W. Va.

Signed J. Goddard