

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 311266

County Guernsey Township Cambridge Section of Township _____
Owner Roy Rominger Address Rt #3 Cambridge O
Location of property North side of Rt 22 East on Co. road 24

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 15'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

Pumping Rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date _____
Static level-depth to water 54' ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Shale</u>	0 Feet	<u>12 Ft.</u>
<u>Sandrock</u>	<u>12</u>	<u>48</u>
<u>gray Slate</u>	<u>48</u>	<u>60</u>
<u>Coal</u>	<u>60</u>	<u>61</u>
<u>Slate</u>	<u>61</u>	<u>65</u>
<u>Shale</u>	<u>65</u>	<u>78</u>

water, 66 ft

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

