

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 312909

County WAYNE Township FRANKLIN Section of Township SOUTH EAST
Owner BEN Egleston Address R.R. I Franklin Ohio
Location of property PEKIN R.D. First line E 123

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 23'
Type of screen _____ Length of screen _____
Type of pump slab Pile
Capacity of pump 600 G.P.H.
Depth of pump setting 78'
Date of completion 8-3-65

BAILING OR PUMPING TEST


Pumping Rate 2 G.P.M. Duration of test 6 hrs.
Drawdown _____ ft. Date _____
Static level-depth to water 20 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by A.J. Asher

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.
TOP SOIL		2
Blue clay	2	11
Loose Rock		25
Lime clay	11	44
Hard lime	25	75
Lime clay	44	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm A.J. Asher Date 8-3-65
Address P.O. Box 285 Carlsburg Signed A.J. Asher

232