

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 314612

County Montgomery Township Madison Section of Township North West
Owner W. M. Johnson Address Dayton, Ohio
Location of property 1/4 Mi. South of Wolf Creek on Licken Ch. Rd.

CONSTRUCTION DETAILS

Casing diameter 6" O.D. Length of casing 21
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

Pumping Rate 10 G.P.M. Duration of test _____ hrs.
Drawdown 5 ft. Date 11-12-65
Static level depth to water 21 ft.
Quality (clear) (cloudy, taste, odor) _____
Pump installed by Owner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>3 Ft.</u>
<u>Rock</u>	<u>3</u>	<u>60</u>
<u>Water at 24</u> <u>+ 50 ft</u>		
<u>1465</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

Wolf Creek Rd
11 mi. N of Madison
W. E.
Snyder Rd
House
Well
S.
See reverse side for instructions

Drilling Firm H. McCullough
Address Verona, Ohio

Date 11-12-65
Signed _____