

# WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL  
OR TYPEWRITER  
DO NOT USE INK.

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
1562 W. First Avenue  
Columbus 12, Ohio

No 314619

County Montgomery Township Madison Section of Township 9  
Owner Donald Wickerson Address Oak Rd - Dayton, Ohio  
Location of property Corner 17 Oak Rd + Shiloh Spring Rd - South East Corner

## CONSTRUCTION DETAILS

Casing diameter 6" O.D. Length of casing 40  
Type of screen \_\_\_\_\_ Length of screen \_\_\_\_\_  
Type of pump Sanmag bl.  
Capacity of pump 1/3 H.P.  
Depth of pump setting \_\_\_\_\_  
Date of completion 11-28-65

## BAILING OR PUMPING TEST

Pumping Rate 20 G.P.M. Duration of test 1 hrs.  
Drawdown 5 ft. Date 10-30-65  
Static level-depth to water 15 ft.  
Quality (clear) cloudy, taste, odor)  
Pump installed by J. McEneaney

## WELL LOG

| Formations<br>Sandstone, shale, limestone,<br>gravel and clay | From   | To     |
|---------------------------------------------------------------|--------|--------|
| Clay                                                          | 0 Feet | 28 Ft. |
| sand/gravel                                                   | 28     | 40     |
| Water -                                                       | 36 ft  |        |
|                                                               | 01     |        |

## SKETCH SHOWING LOCATION

Locate in reference to numbered  
State Highways, St. Intersections, County roads, etc.

West Brook Rd.

Shiloh Spring Rd.

Union Rd.

1465

See reverse side for instructions

Drilling Firm J. McEneaney  
Address \_\_\_\_\_

Date 10-30-65  
Signed \_\_\_\_\_