

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

34
Nº 317934

County Trembly Township Bristol Section of Township South East
Owner Ronald Mahan Address P.O. #1 Bristolville Ohio
Location of property 1/4 mi East of Rt 45 on Pierce Rd

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 48'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 12 G.P.M. Duration of test _____ hrs.
Drawdown 50 ft. Date _____
Static level-depth to water 35 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay, Sand & Gravel</u>	0 Feet	<u>48</u> Ft.
<u>Shale</u>	<u>45'</u>	<u>55'</u>
<u>Clay Sand & Rock</u>	<u>55'</u>	<u>66'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Fred Newbury Gorman & Hardy Date Oct 13, 1967
Address Bristolville Ohio Signed Fred Newbury

34