

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 318184

County MIAMI Township BETHEL Section of Township So. EAST
Owner MARK ALLEN Address MEDWAY, OHIO
Location of property 7255 S. PALMER Rd

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 24'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date 8'6"
Static level-depth to water _____ ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>clay</u>	0 Feet	<u>8' Ft.</u>
<u>limestone</u>	<u>8'</u>	<u>50'</u>
	<u>50'</u>	<u>58'</u>
	<u>58'</u>	
<u>Water 25'</u>		

SKETCH SHOWING LOCATION 363

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm C.A.P. Law
Address 9405 Lower Valley Pk.
New Carlisle Ohio

Date 8-21-68
Signed C.A.P. Law