

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 318722

County Ross Township Union Section of Township _____
Owner Tray Mark Address Chillicothe, O. R.R.#1
Location of property at Andersonville, on state pte. 104

CONSTRUCTION DETAILS

Casing diameter 6" O.D. Length of casing 35
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 8 G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date March 15/1965
Static level-depth to water 28 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	_____ Ft.
<u>Clay</u>		<u>24</u>
<u>sand</u>	<u>24</u>	<u>30</u>
<u>gravel</u>	<u>30</u>	<u>37</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm James Butler
Address Chillicothe, O. R.R.#7

Date March 15 1965
Signed James Butler

LOCATED

19