

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, OhioN^o 318723County Ross Township Scotts Section of TownshipOwner D. J. Darby Address Chillicothe RR#Location of property 3 1/2 miles south of Chillicothe on Lewis Beck Road

CONSTRUCTION DETAILS

Casing diameter 6" O.D. Length of casing 50

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST


Pumping Rate 4 G.P.M. Duration of test 2 hrs.Drawdown 6 ft. Date March 29, 1965Static level-depth to water 38 ft.Quality (clear, cloudy, taste, odor) Clear

Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.
<u>Clay</u>		<u>29</u>
<u>Gravel</u>	<u>29</u>	<u>32</u>
<u>blue Clay</u>	<u>32</u>	<u>40</u>
<u>sand and gravel</u>	<u>40</u>	<u>50</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

See reverse side for instructions

Drilling Firm James BethelAddress Chillicothe O.P.Date March 29, 1965Signed James Bethel

242