

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 318724

County Ross Township Twin Section of Township

Owner Paul Bethel Address Chillicothe O, RR#3

Location of property 2 1/2 miles west of State mill on Cat tail Road

CONSTRUCTION DETAILS

Casing diameter 6" O.D. Length of casing 97 ft.
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion

BAILING OR PUMPING TEST


Pumping Rate 6 G.P.M. Duration of test 2 hrs.
Drawdown 30 ft. Date Oct 23
Static level-depth to water 48 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.
<u>top soil.</u>		<u>5</u>
<u>gravel</u>	<u>5</u>	<u>30</u>
<u>sand</u>	<u>30</u>	<u>48</u>
<u>clay</u>	<u>40</u>	<u>70</u>
<u>sand</u>	<u>70</u>	<u>95</u>
<u>hard pan</u>	<u>95</u>	<u>97</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm James Bethel
Address Chillicothe O, RR#3

Date Oct. 23 1965
Signed James Bethel