

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 319605

County Holmes Township Clark Section of Township 5Owner Orie Oswald Address CharmLocation of property 1 1/2 mi west of Charm

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 94' 10"

Type of screen _____ Length of screen _____

Type of pump _____

Capacity of pump _____

Depth of pump setting _____

Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 10 G.P.M. Duration of test 1 hrs.Drawdown 20 ft. Date Oct 30 - 1964Static level-depth to water 280 ft.Quality (clear, cloudy, taste, odor) _____

Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	30 Ft.
sand rock	30	50
blue shale	20	53
limestone	3	113
blue shale	60	143
sand rock	40	213
blue shale	70	300
sand rock	87	320
blue shale	20	340
sand rock	40	360

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.Drilling Firm V. J. KasuAddress RD 2 CharmDate Oct 30 - 1964Signed V. J. Kasu

2