

WE LOG AND DRILLING REPORT

84

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 319612

County Wayne Township Chester Section of Township 25
Owner San Hinton Address Worster Dr, Rt 5
Location of property 1 mi Southeast of New Pittsburg S.R. 40

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 51' 11"
Type of screen _____ Length of screen _____
Type of pump myers sub
Capacity of pump 13.8 gpm
Depth of pump setting 105'
Date of completion _____

BAILING OR PUMPING TEST

Pumping Rate 13 G.P.M. Duration of test 1 hrs.
Drawdown 10 ft. Date June
Static level-depth to water 63 + 10 = 73 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by V. J. Kaser

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Brown Clay</u>	<u>0 Feet</u>	<u>20 Ft.</u>
<u>Blue shale</u>	<u>20</u>	<u>80</u>
<u>sand Rock</u>	<u>25</u>	<u>105</u>
<u>Blue shale</u>	<u>10</u>	<u>115</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

NEW PITTSBURGH

S.

See reverse side for instructions

Drilling Firm V. J. KaserDate 6-10-1955Address Shreveport 2Signed V. J. Kaser

270