

WELL LOG AND DRILLING REPORT

ORIGINAL

2 ✓

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 319703

County Coshocton Township Bethlehem Section of Township

Owner L. W. Randles Address Warsaw RT 1

Location of property 1 1/2 mile north of US 36 on Twp Road no 43

CONSTRUCTION DETAILS

Casing diameter 5 1/2" O.D. Length of casing 161 ft.
Type of screen none Length of screen
Type of pump Submersible
Capacity of pump 10 G.P.M.
Depth of pump setting 370 ft.
Date of completion 8-14-65

BAILING OR PUMPING TEST

Pumping Rate 10 G.P.M. Duration of test 2 1/2 hrs.
Drawdown 60 ft. Date 8-12-65
Static level-depth to water 211 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by L. W. Randles


WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Top Soil	0 Feet	1 Ft.
Grey clay	1	19
Grey shale	19	32
Limestone	32	35
Blue shale	35	55
Limestone	55	58
Shale	58	84
Sandstone	84	92
Shale	92	134
Sandstone	134	138
Blue shale	138	161
Grey shale	161	410
Sandstone	410	413
Grey shale	413	448
White Sandstone	448	476

Water 468 ft.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm D. L. Fessler

Address Box 7 Walhonding

Date 8-14-65

Signed D. L. Fessler