

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

(28)
Nº 321396

County MEDINA Township WADSWORTH Section of Township _____
Owner DALE KIMES Address RD# WADSWORTH, O.
Location of property ADDDOT 1/2 MI. SOUTH OF RT 97 ON RT 51

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 29'
Type of screen _____ Length of screen _____
Type of pump 1/3 HP S.W. JET
Capacity of pump 460 GPH
Depth of pump setting 20'
Date of completion _____

BAILING OR PUMPING TEST

Pumping Rate 30 G.P.M. Duration of test 2 hrs.
Drawdown 6 ft. Date 3/24/66
Static level-depth to water 11 ft.
Quality (clear, cloudy, taste, odor) CLOUDY
Pump installed by DRILLER


WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
CLAY, YELLOW & SAND	0 Feet	20' Ft.
CLAY, GRAY & SAND	20'	26'
SAND & GRAVEL	26'	30'

WATER AT 29'
TESTED PUMPED
2 HRS

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm WADSWORTH SUPPLY
Address 8040 RIDGE RD.
WADSWORTH, O.

Date 3/24/66
Signed [Signature]

LOCATED
153

37 Seville