

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 321397

County SUMMIT Township NORTON Section of Township

Owner CHARLIE BORDNER JR. Address JANE DR. BARBERTON, O.

Location of property LOT # 43 5079 Jean

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 43'
Type of screen NONE Length of screen
Type of pump 1/2 HP SUBMERSIBLE
Capacity of pump 80 GPM
Depth of pump setting 120'
Date of completion

BAILING OR PUMPING TEST

Pumping Rate 12 G.P.M. Duration of test 2 hrs.
Drawdown NONE ft. Date 3/23/66
Static level-depth to water 105 ft.
Quality (clear, cloudy, taste, odor) CLOUDY
Pump installed by DRILLER

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay


From

To

Formations	From	To
CLAY, YELLOW & SAND	0 Feet	20' Ft.
CLAY, GRAY & SAND	20'	41'
ROCK, SHALE GRAY D.	41'	55'
ROCK, SHALE GRAY L.	55'	70'
ROCK, SHALE GRAY D.	70'	97'
ROCK, PEBBLE YELLOW	97'	100'
ROCK, GRAY SAND	100'	130'

WATER AT 120'

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm WADSWORTH SUPPLY

Date 3/23/66

Address 8040 RIDGE RD
WADSWORTH, O.

Signed Eugene [Signature]