

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

OK
No 321927
2062
18

County MORROW Township CANAAN Section of Township 18
Owner RICHARD E. COOPER Address Route #2 CALEDONIA OHIO
Location of property on Road 67. 1/4 mile EAST of Route 746

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 56'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date _____
Static level-depth to water 5 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>YELLOW CLAY</u>	0 Feet	<u>8</u> Ft.
<u>BLUE CLAY</u>	<u>8</u>	<u>21</u>
<u>SAND</u>	<u>21</u>	<u>23</u>
<u>BLUE CLAY</u>	<u>23</u>	<u>39</u>
<u>SAND</u>	<u>39</u>	<u>40</u>
<u>BLUE CLAY</u>	<u>40</u>	<u>52</u>
<u>SAND & GRAVEL</u>	<u>52</u>	<u>56</u>
<u>WATER 54'</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm CARL MESSINGER
Address 2301 SMELTZER ROAD
MARION OHIO

Date July 24 1968
Signed Carl Messenger

(41)