

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

Nº 321931

County MARION Township PLEASANT Section of Township _____
Owner RONALD OSBORNE Address 527 MARION-CARDINGTON RD. WEST
Marion Ohio.
Location of property Road (136) MARION-CARDINGTON West. 1 MI

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST
Casing diameter <u>4 1/4"</u> Length of casing <u>35</u>	Pumping Rate _____ G.P.M. Duration of test _____ hrs.
Type of screen _____ Length of screen _____	Drawdown _____ ft. Date _____
Type of pump _____	Static level-depth to water <u>18'</u> ft.
Capacity of pump _____	Quality (clear, cloudy, taste, odor) _____
Depth of pump setting _____	Pump installed by _____
Date of completion _____	

WELL LOG			SKETCH SHOWING LOCATION
Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
<u>YELLOW CLAY</u>	<u>0 Feet</u>	<u>9 Ft.</u>	N. E. See reverse side for instructions
<u>BLUE CLAY</u>	<u>9</u>	<u>26</u>	
<u>GRAVEL</u>	<u>26</u>	<u>27</u>	
<u>BLUE CLAY</u>	<u>27</u>	<u>29</u>	
<u>LIMESTONE</u>	<u>29</u>	<u>60</u>	

WATER 59'

Drilling Firm CARL MESSINGER
Address 2301 SMELTZER ROAD
MARION OHIO

Date OCT 2 1969
Signed Carl Messenger