

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 323148

CENTER

County NOBLE Township BUFFALO Section of Township ✓

Owner ALVA WATSON Address SARASVILLE, OHIO

Location of property 1/2 mi. N.W. of Sarasville on S.T. Rt. 146

CONSTRUCTION DETAILS

Casing diameter 6 1/4" I.D. Length of casing 20'
Type of screen PLASTIC 5" I.D. well liner Length of screen 157'
Type of pump ✓
Capacity of pump ✓
Depth of pump setting ✓
Date of completion ✓

BAILING OR PUMPING TEST

Pumping Rate 1 1/2 G.P.M. Duration of test 2 hrs.
Drawdown ✓ ft. Date 4.9.66
Static level-depth to water 21 ft.
Quality (clear, cloudy, taste, odor) GOOD
Pump installed by ✓


WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
RED CLAY	0 Feet	15 Ft.
BROWN SHALE	15	16
GRAY SHALE	16	21
LIME STONE	21	22
GRAY SHALE	22	29
LIME STONE	29	30
SANDY SHALE	30	37
LIME STONE	37	39
DARK GRAY SHALE	39	50
LIME STONE	50	52
SAND ROCK	52	57
LIME STONE	57	59
DARK SHALE	59	67
COAL	67	68
FIRE CLAY	68	70
GRAY SHALE	70	85
RED SHALE	85	114
GRAY SHALE	114	137
SAND ROCK	137	155
GRAY SHALE	155	160

W - 39 - 67 - 95

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm

Address

Date

Signed

M. Farland Drilling
Fl. 3 - Cambridge, O.

5/10/66

John M. Farland

(3)