

WELL LOG AND DRILLING REPORT

ORIGINAL

29

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 323385

County Franklin Township Warren Section of Township 8 East No.
Owner Harry W Edith & Ronald Address 6023 Eagle Creek Rd Leamington
Location of property _____

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 39¹⁰
Type of screen None Length of screen None
Type of pump Electric
Capacity of pump _____
Depth of pump setting _____
Date of completion Oct 19-65

BAILING OR PUMPING TEST

Pumping Rate 18 G.P.M. Duration of test 2 hrs.
Drawdown 15 ft. Date Nov 29 66
Static level-depth to water 20 ft.
Quality (clear, cloudy, taste, odor) clear
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
yellow Clay	0 Feet	12 Ft.
Blue Clay	12	32
Shale Rock	32	67
Water at 64-67		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.
W. Eagle Creek 1 1/2 mi to Leamington

S.
See reverse side for instructions

Drilling Firm Wareham
Address RD #2 Newton Falls O

Date Nov 29-65
Signed W.J. Wareham

29