

WELL LOG AND DRILLING REPORT

1st (21) ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus 12, Ohio

No 324102

County Hayette Township Concord Section of Township

Owner Stacey Anders Address

Location of property Dollars Road off Route 72

CONSTRUCTION DETAILS

Casing diameter 5 5/8" Length of casing 42'
Type of screen 0 Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion Dec 16, 1964

BAILING OR PUMPING TEST


Pumping Rate 30 G.P.M. Duration of test 2 hrs.
Drawdown 4 ft. Date Dec. 16, 1964
Static level-depth to water 15' ft.
Quality (clear, cloudy, taste, odor) cloudy
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.
old well	0	15'
sand	15'	30'
blue clay	30'	42'
limestone	42'	60' W.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Butledge Well Drilling Date Dec. 23, 1964
Address Rural Route #4 Signed Rodney J. Butledge

