

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No 325661

County STARK Township PERRY Section of Township 36
Owner REARICK, M. E. Address 4532 BETHUNIA CH
Location of property 11900 - BETHUNIA RD #101

CONSTRUCTION DETAILS

Casing diameter 4 in Length of casing 28 FT
Type of screen 1/2 in Length of screen 1/2 in
Type of pump DEEP WELL
Capacity of pump 2 G.P.M.
Depth of pump setting 40 FT
Date of completion June 26-69

BAILING OR PUMPING TEST


Pumping Rate 6 G.P.M. Duration of test 2 hrs.
Drawdown 2 ft. Date June 25-69
Static level-depth to water 19 ft.
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by DEEBO

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.
<u>CLAY SHALE</u>	<u>0</u>	<u>22</u>
<u>CLAY SHALE</u>	<u>8</u>	<u>30</u>
<u>CLAY SHALE</u>	<u>17</u>	<u>50</u>
<u>CLAY SHALE</u>	<u>10</u>	<u>60</u>
<u>WATER FROM 30 TO 60 FT</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm REARICK, M. E.

Date June 25-69

Address 4532 BETHUNIA CH

Signed REARICK, M. E.

*If additional space is needed to complete well log, use next consecutive numbered form.