

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No 326199

899

County Franklin Township Plasent Section of Township 7-8st
Owner John W. Garber Address 6233 Oakhurst Dr
Location of property Between Johnston - Grove City Rd

CONSTRUCTION DETAILS

Casing diameter 4 1/2" Length of casing 117
Type of screen None Length of screen
Type of pump 1/2 hp sumner
Capacity of pump 82 GPM
Depth of pump setting 88 ft
Date of completion 8-7-68

BAILING OR PUMPING TEST


Pumping Rate 15 G.P.M. Duration of test 2 hrs.
Drawdown None ft. Date 7-5-68
Static level-depth to water 6.2 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by Brunt Stelton

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>34 Ft.</u>
<u>Sand / Clay</u>	<u>34</u>	<u>44</u>
<u>B Clay</u>	<u>44</u>	<u>86</u>
<u>Sand</u>	<u>86</u>	<u>93</u>
<u>Clay</u>	<u>93</u>	<u>103</u>
<u>Sand / Shale</u>	<u>103</u>	<u>117</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Brunt Stelton Date 8-16-68
Address 2445 Middle Signed Brunt Stelton

*If additional space is needed to complete well log, use next consecutive numbered form.