62

# WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

№ 329273

County Columbiana Township Madison Section of Township Sec 34

Owner Jerry Nickles Address RD#1 Wellsville, Ohio

Location of property State Rt#45 1½ mile North Wellsville

## CONSTRUCTION DETAILS

Casing diameter 6"/4 Length of casing 21'1"

Type of screen ..... Length of screen .....

Type of pump .....

Capacity of pump .....

Depth of pump setting .....

Date of completion .....

## BAILING OR PUMPING TEST

Pumping Rate 2 G.P.M. Duration of test ½ hrs.

Drawdown 59 ft. Date 12/14/66

Static level-depth to water 158' 126' ft.

Quality (clear, cloudy, taste, odor) .....

Pump installed by .....

## WELL LOG*

| Formations Sandstone, shale, limestone, gravel and clay | From | To |
|---|---|---|
| Shale | 0 Feet | 13 Ft. |
| Slate | 13 | 60 |
| Sand Rock | 60 | 126 |
| Slate | 126 | 158 |
| Water at 28'+126' | | |

## SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.




See reverse side for instructions

Drilling Firm Miller Bros. Drilling Date 12/19/66

Address River Rd., East Liverpool, Ohio. Signed [illegible]

*If additional space is needed to complete well log, use next consecutive numbered form.

52