WELL LOG AND DRILLING REPORT

ORIGINAL
22C

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

PLEASE USE PENCIL OR TYPEWRITER

DO NOT USE INK.

№ 336483

34

County Paulding Township Carryall Section of Township Carryall

Owner Arthur Monroe Address Antwerp Ohio

Location of property Antwerp village RT 49 south in town

CONSTRUCTION DETAILS

Casing diameter 4 Length of casing 45

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST

Pumping Rate 9 G.P.M. Duration of test 2 hrs.

Drawdown 45 ft. Date Sept 6 1972

Static level-depth to water 29 ft.

Quality (clear, cloudy, taste, odor) taste

Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
20 yellow clay	0 Feet	20 Ft.
20 blue clay	20	40
5 sand	40	45
32 sand rock	45	77
77		

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm L B Derck Date Sept 6 1972

Address Antwerp Ohio R.R.1 Signed Francis Derck

*If additional space is needed to complete well log, use next consecutive numbered form.

46