

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No 337641

County Guernsey Township Center Section of Township 5
Owner Howard Arnold #2 Address Rt 3 Cambridge O.
Location of property AT Lakerien Addn. jct. of U.S. 22 & Card. 57

CONSTRUCTION DETAILS

Casing diameter 8 1/2" Length of casing 26'
Type of screen 5" Liner Length of screen 9 ft. pack
Type of pump Subm.
Capacity of pump To be installed
Depth of pump setting by owner
Date of completion by owner

BAILING OR PUMPING TEST


Pumping Rate 3 1/2 G.P.M. Duration of test 24 hrs.
Drawdown - ft. Date 1-20-67
Static level-depth to water 12' ft.
Quality (clear, cloudy, taste, odor) good Taste - Clear
Pump installed by Owner

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>4 Ft.</u>
<u>Sandy Shale</u>	<u>4</u>	<u>12</u>
<u>Gray Shale</u>	<u>12</u>	<u>20</u>
<u>Sandstone</u>	<u>20</u>	<u>28</u>
<u>Blue Core</u>	<u>28</u>	<u>40</u>
<u>Fireclay</u>	<u>40</u>	<u>50</u>
<u>Sandrock</u>	<u>50</u>	<u>62</u>
<u>Blue P. Lime</u>	<u>62</u>	<u>72</u>
<u>Fireclay</u>	<u>72</u>	<u>80</u>
<u>Water at 50' & 70'</u>		
<u>3 1/2 GPM.</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Marlett Drilling
Address Rt 3 Cambridge

Date 1-20-67
Signed Donna Marlett

*If additional space is needed to complete well log, use next consecutive numbered form.

11A