WELL LOG AND DRILLING REPORT

ORIGINAL

18N

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

PLEASE USE PENCIL OR TYPEWRITER

DO NOT USE INK.

№ 339578

County Coshocton Township OXFORD Section of Township

Owner SHERMAN ART Address R.3 NEWCOMERSTOWN, O

Location of property LOT NO. 308 EAST PART of ISLETA

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing 62'

Type of screen SLOTTED Length of screen 8'

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST

~~Pumping~~ BAILER Rate 20 G.P.M. Duration of test 1 hrs.

Drawdown 2 ft. Date 10-9-69

Static level-depth to water 40 ft.

Quality (clear, cloudy, taste, odor) CLEAR

NO TASTE OR ODOR

Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
Sandy GRAVEL	0 Feet	62 Ft
WATER AT 40'		

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.

58610 Wolfe St N.



See reverse side for instructions

Drilling Firm McCoy Drilling Date 10-9-69

Address R.2 Frazeysburg Signed Lewis McCoy

*If additional space is needed to complete well log, use next consecutive numbered form.

72