

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

No 341397

Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

County Geauga Township Claridon Section of Township 5.

Owner Jewish Community Center Address Cleveland

Location of property Came Wisc, Taylor Wells Rd. Well no. 1

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing _____
Type of screen _____ Length of screen _____
Type of pump Submersible
Capacity of pump 50 gpm
Depth of pump setting 150
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate 50 G.P.M. Duration of test 1 hrs.
Drawdown 160 ft. Date _____
Static level-depth to water 34 ft.
Quality (clear, cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	137 Ft.
<u>Layers Shale & Sandstone</u>		195
<u>Well 3 years old - Acid treated and drilled deeper</u>		
<u>Well no. 1</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Frederickson Well Drilling
Address Newbury, O.

Date Dec 67
Signed D. Frederickson

*If additional space is needed to complete well log, use next consecutive numbered form.