

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER

DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

No 347977

County Trembly Township Bristol Section of Township N.E.
Owner Clayton Wildman Address Bloomfield, O.R. 1
Location of property on Oakfield North, 1/2 mi N Hyde Oakfield Rd

CONSTRUCTION DETAILS

Casing diameter 5 3/8 Length of casing 65
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping Rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date Oct 10-67
Static level-depth to water 28 ft.
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	<u>0 Feet</u>	<u>17 Ft.</u>
<u>Clay & Sand</u>	<u>17</u>	<u>60</u>
<u>Shale</u>	<u>60</u>	<u>65</u>
<u>Sand Rock</u>	<u>65</u>	<u>75</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm M.V. Walters
Address Bristolville, O

Date Oct 10-67
Signed M.V. Walters

*If additional space is needed to complete well log, use next consecutive numbered form.