ORIGINAL

175

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio 43212

PLEASE USE PENCIL OR TYPEWRITER

DO NOT USE INK.

№ 348439

County OTTAWA Township BENTON Section of Township 36

Owner MR LLOYD GRAU Address OAK HARBOR O

Location of property BENTON CARROLL RD, (C23)

CONSTRUCTION DETAILS

Casing diameter 4 7/8 Length of casing 41

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST

Pumping Rate 7 G.P.M. Duration of test hrs.

Drawdown 50 ft. Date

Static level-depth to water 18 ft.

Quality (clear, cloudy, taste, odor) CLEAR

Pump installed by

WELL LOG*

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
CLAY	–	34
LIMESTONE	34	125–

SKETCH SHOWING LOCATION

Locate in reference to numbered State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm DEWEY WIDMER Date NOV. 22 '69

Address MILLBURY O Signed Dewey Widmer

*If additional space is needed to complete well log, use next consecutive numbered form.

LAST UNTIL SPRING RAIN.

148